

## Wire & Cable testers : MS6818

### Technical Parameters of Transmitter

Output Signal	125kHz
External Voltage	DC12~400V AC12~400V(50~60Hz) $\pm 2.5\%$
Fuse	F0.5A 1000V
MIN Current	about 31mA
MAX Current	about 115mA
In Work	0~40°C, with MAX relative humidity of 80%
In Storage	-20~60°C, with MAX relative humidity of 80%
Altitude	<2000m

### Technical Parameters of Receiver

Depth of Tracking	The Depth of Tracking Depends on the Material and Specific Applications
Cable	Single pole application: about 0~2m
Locating	Dual pole application: about 0~0.5m
Mode	Single loop line: Up to 2.5m
MIN Current	about 32mA
MAX Current	about 89mA
In Work	0~40°C, with MAX relative humidity of 80%
In Storage	-20~60°C, with MAX relative humidity of 80%
Altitude	<2000m